








Dimensions



Pass Through Port



w/ Gasket Removed



Hole Saw

